## **MONTHLY EDITION NUMBER 36**

ISSUED BY: COMMANDER, THIRTEENTH COAST GUARD DISTRICT (oan)

915 Second Avenue, Seattle, Washington 98174-1067 Telephone (206) 220-7270 FAX # (206) 220-7285

## BROADCAST NOTICES TO MARINERS (BNMs)

This Local Notice to Mariners (LNM) includes information concerning waterways in the Thirteenth Coast Guard District promulgated by the following broadcasts:

BNM 0846-97 to 0857-97

LIGHT LIST REFERENCE: COMDTINST M16502.6, Light List Volume VI, 1997 Edition

\*\*\*Electronic Bulletin Board Service: (703) 313-5910\*\*\*

300 to 28.8 bps, 8 data bits, no parity, 1 stop bit

\*\*NIS watchstander, 24 hours a day at (703) 313-5900\*\*

\*INTERNET ADDRESS\*

HTTP://www.navcen.uscg.mil

or

FTP://ftp.navcen.uscg.mil

## I. SPECIAL NOTICE

# CANADA - REGULATORY REQUIREMENTS FOR FOREIGN COMMERCIAL FISHING VESSEL ENTERING CANADIAN WATERS -

The Coastal Fisheries Protection regulations were amended 16 July 1996 to introduce new requirements for foreign commercial fishing vessels. Department of Fisheries and Oceans is reminding affected parties that these requirements are still in effect.

Please be advised that masters of foreign commercial fishing vessels must, as soon as reasonably possible, after entering Canadian waters:

- 1. Notify the Department of Fisheries and Oceans of the name, flag, state, location, route and destination of the vessel and of the circumstances under which it entered Canadian fisheries waters.
- 2. Ensure that all fishing gear on board the vessel is stowed below deck or otherwise removed from the place where it is normally used for fishing and placed where it is not readily available for fishing, and
- 3. Where requested by a Protection Officer, proceed to a specified location so that a vessel inspection can be conducted.

These requirements do not apply to foreign fishing vessels operating under a Canadian fishing license. In addition, they do not apply to United States sport fishing vessels conducting normal sport fishing activities.

Affected vessel masters can notify Department of Fisheries and Oceans on the following Marine Communications and Traffic Service channels 71, 11, or 22A. At that time, fishery officials will advise if a vessel inspection is required and provide information on gear stowage.

The primary reason for the requirements is conservation. Failure to comply with requirements is viewed as a serious offense. The Coastal Fisheries Protection Act specifies a maximum penalty of \$100,000.

#### USA - LORAN-C TERMINATION STUDY -

The 1996 Federal Radionavigation Plan calls for the termination of Loran-C operations in the year 2000. The U.S. Department of Transportation (DOT) is undertaking a congressionally mandated review of the decision to cease operations. Booz-Allen & Hamilton, Inc., has been retained to assess the technical merits of extending Loran-C service beyond the year 2000 and to conduct a cost/benefit analysis of such an action. Booz-Allen will host a Users Conference, during which representatives of various Loran-C users will present information related to the system and its present and future use. The conference is scheduled for 08-09 September 1997, at Booz-Allen's headquarters in McLean, VA.

Because of the schedule and location, the conference may not provide every segment of the user community the opportunity to have input. Therefore, DOT is also soliciting written input from

individuals and organizations prior to, during and following the conference. These inputs may be mailed to:

DOT Loran-C Study Comments c/o Joseph R. Davis Booz-Allen & Hamilton, Inc. 8251 Greensboro Dr. McLean, VA 22102

Telephone comments will not be accepted. E-mail comments may be forwarded to: loranc@bah.com. FAX comments may be sent to (703)917-3023. comments may be sent 24 hours a day. Comments are being solicited on any technical, operational or economic issue(s) associated with the proposed action. Comments should be factual, and if possible provide verifiable reference to the source of any data cited. Commentors may call (703)902-4671 during normal business hours (0800 to 1700 EST) to confirm receipt. All comments should identify the originator and provide some means (mail, telephone or E-mail) to allow return contact with the originator. Commentors should identify the specific Loran-C user community/communities (maritime, aviation, weather, timing and synchronization, etc.) they represent, and the specific use made (type of aircraft, vessel or other platform, where used, what other navigation systems are used, and typical navigation activity). In addition, comments should address safety, reliability and other system performance issues.

Inputs will be accepted until 15 December 1997; however, early submission will ensure time for the contractor and DOT to address key issues in the cost/benifit analysis and other technical reports.

## WASHINGTON - SEQUIM - Outfall Work -

Outfall extension operations in Sequim, on the east side of Gibson Spit will commence 29 September and conclude the first week of November 1997. Floating equipment will have anchor lines and mooring buoys deployed during these operations. Proper lights and day shapes will be deployed. The mooring buoys will show a flashing Yellow light. The floating equipment will monitor VHF-FM Channels 14 and 16. Mariners are urged to use extreme caution when transiting in the vicinity of the floating equipment. Chart 18471

# REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT I. SPECIAL NOTICE (continued)

OREGON - COLUMBIA RIVER ENTRANCE - Deployment of Hydrodynamic Measurement Instruments

Hydrodynamic measurement instruments have been deployed at the mouth of the Columbia River on the seabed and will remain for a period of 30-60 days. There will be subsequent deployments of 60-100 days that will continue through March 1998 or later. There are three location within four miles of the entrance channel. The positions are listed below:

INSTRUME	NT NUMBER	POSITION		DEPTH (MLLW)
1	46 <sup>2</sup> 14'46.7"N	124 <sup>2</sup> 07'25.8"W	47 ft	
2	46 <sup>2</sup> 14'09.9"N	124 <sup>2</sup> 10'32.2"W	65 ft	
3	46 <sup>2</sup> 13'56.7"N	124 <sup>2</sup> 11'08.6"W	110 ft	

WASHINGTON - SEACOAST - Oceanographic Research Operations -

The R/V THOMAS G. THOMPSON (KTDQ) will be conducting oceanographic research operations in the following areas from 03 October through 16 October 1997:

POSITION 47<sup>2</sup>59'N 125<sup>2</sup>38'W 47<sup>2</sup>59'N 125<sup>2</sup>23'W 48<sup>2</sup>09'N 125<sup>2</sup>38'W 48<sup>2</sup>09'N 125<sup>2</sup>23'W

Mariners are requested to give a 1 nautical mile berth. Charts 18480 and 18500

## WASHINGTON - GRAYS HARBOR - DEPLOYMENT OF CURRENT METER ARRAY -

A current meter array has been deployed off Grays Harbor in approximate position 46<sup>2</sup>-51.7' N and 124<sup>2</sup>-14.8' W, approximately .75 NM Southwest of the Grays Harbor Buoy in 21 fathoms of water. The array is bottom anchored with the top float extending to 60 feet below the surface.

WASHINGTON - STRAIT OF JUAN DE FUCA - PORT ANGELES - Multi Agency Operation - Commencing 1000 local 18 September through 1200 local 21 September 1997 multiple agencies will engage in surface and subsurface exercises. These operations will be on a 24 hour basis, encompassing Coast Guard Group Port Angeles and the inner bay. Approximate exercise positions are bounded by 48²07′00″N 123²23′00″W to 48²08′30″N 123²27′00″W and southwestward to shore. There will be 10 to 15 small boats involved in the operation. Diver operations will be in the water along the beach between the end of Ediz Hook and the Coast Guard T-pier. Mariners are requested to stay clear of the operation area.

Chart 18468

## WASHINGTON - PORT ANGELES - PORT OF PORT ANGELES OUTFALL WORK -

Construction has commenced on the outfall in Port Angeles and will finish the second week in September. Floating equipment will have anchor lines and buoys out during construction. The buoys will be lighted showing a flashing yellow light. Mariners are urged to use extreme caution when transiting the area. Chart 18468

#### OREGON - WILLAMETTE RIVER - Steel Bridge - Bridge Information -

The draw need not open from 0815 local to 1330 local on 27 September 1997, to accommodate the Portland Marathon.

Chart 18526

#### WASHINGTON - LAKE WASHINGTON SHIP CANAL - Bridge Information -

The draw of the Fremont Bridge need not open both leaves unless one hour notice is provided Monday through Friday 0600 local to 2200 local and from 0700 local to 2200 local on Saturdays. Single-leaf openings will be provided on signal per the normal operating schedule. Vertical clearance may be reduced by three feet when the debris containment system is in place during the painting project. These special operations, currently in effect, are extended to 01 October 1997. Chart 18447

#### II. DISCREPANCIES - DISCREPANCIES CORRECTED

# THE FOLLOWING AIDS TO NAVIGATION ARE NOT WATCHING AS ADVERTISED IN THE LIGHT LIST VOLUME VI, THIRTEENTH DISTRICT SECTION:

- Underlined text denotes new discrepancy since last LNM.

#### FEDERAL AIDS

LL#	Aid Name	Status	Chart	BNM	LNM		
00760	CAPI	E FLATTE	RY LIG	HT		IMPROPER CHARACTERIS	TIC
18485	0761-97	31/97					
09275	UMP	QUA RIV	ER LB 6	iΑ		OFF STATION	18584
0604-97	23/97	1					

09285 1322-96		WINCHESTER BAY HBR ENTRANCE 49/96	DBN 1	MISSING		18584
09315 96	49/96	UMPQUA RIVER LIGHT 15	MISSIN	NG	18584	1329-
11165 0769-97		WILLOW DIKE LIGHT 26 34/97	EXTIN	GUISHED		18524
11405 97		RNMENT ISLAND MIDDLE RF LIGHT		OBSCURED	18531	0807-
11555 18531	0803-97	WASHOUGAL UPPER RANGE REAR I 33/97	LIGHT	REDUCED INT	ENSITY	
15190 0036-97		WILLAPA BAY ENTRANCE BUOY 8 02/97		MISSING		18504
15585		POINT CHEHALIS RANGE FRONT LIC 0430-97 15/97	GHT	IMPROPER CH	ARACT	ERISTIC
15615	18502	GRAYS HARBOR SOUTH REACH A R 0416-97 15/97	R LIGH	TMISSING TOP	DAYBO	ARD
15965 0536-97		JOHNS RIVER DAYBEACON 3 20/97	DAYB	OARDS MISSIN	G	18502
16830 0698-97		BLAKELY ROCK LIGHT 28/97	EXTIN	GUISHED		18449
17225 18474	0686-97	POINT EVANS LIGHT 4 7 28/97	IMPRO	PER CHARACT	ERISTIC	
18850 0198-95		LACONNER RANGE FRONT LIGHT 18 08/95	3	MISSING		18427
19000 0537-97		CAP SANTE DAYBEACON 3 20/97	DESTR	OYED		18427
19970 18421	0800-97	INTERNATIONAL BOUNDARY A RF I 33/97	LIGHT	EXTINGUISHE	D	
PRIVAT	E AIDS					
LL # 16850 97	Aid Nat 35/97	me Status Chart BNM LNM SHIPMATES ЦGНТ	LT EX	Γ	18441	0833-
		s are cautioned that portions of missing stru	ictures m	ay remain.		

NOTE: Mariners are cautioned that portions of missing structures may remain.

THE FOLLOWING AIDS TO NAVIGATION DISCREPANCIES HAVE REEN CO.

THE FOLLOWING AIDS TO NAVIGATION DISCREPANCIES HAVE BEEN CORRECTED SINCE THE LAST LOCAL NOTICE TO MARINERS:

# II. DISCREPANCIES - DISCREPANCIES CORRECTED (continued)

## FEDERAL AIDS

LL # Aid Name Status Chart BNM LNM

## PRIVATE AIDS

LL# Aid Name Status Chart BNM LNM

17535 POINT HUDSON MARINA LIGHT TEMP DISCONTINUED

18441 0450-97 16/97

# III. TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED

LEGEND: TRUB = Temporary Unlighted Buoy

TRLB = Temporary Lighted Buoy

TRLT = Temporary Light

THE FOLLOWING AIDS TO NAVIGATION HAVE BEEN TEMPORARILY CHANGED:

LL # Aid Name Status Chart BNM LNM

09285		WINCHESTER BAY HBR ENTRANCE	DBN 1	TRUB		18584	1322-
96	49/96						
09315		UMPQUA RIVER LIGHT 15	TRLB		18584	1329-96	5
49/96							
09520		SIUSLAW RIVER CHANNEL DBN 14		TRUB			18583
0238-96		08/96					
09560		SIUSLAW RIVER CHANNEL DAYBEA	CON 26	TRUB			18583
0351-96		09/96					
09856		GARIBALDI CHANNEL LT 14	TRUB			18558	0953-
95	32/95						
11365		GOVERNMENT ISLAND SOUTH CH I	DBN 19	TRUB			18531
0674-96		19/96					
16790		SHILSHOLE BAY BREAKWATER LIGH	HT 3	SOUNI	) SIGNA	L	
DISCON	ITINUE	D 18446 1315-96 48/96					
19005		CAP SANTE DAYBEACON 3	TRUB			18427	0550-
97	20/97						

10504 1000

THE FOLLOWING TEMPORARY AIDS TO NAVIGATION HAVE EITHER BEEN RESTORED TO NORMAL OPERATION OR DISCONTINUED:

LL# Aid Name Status Chart BNM LNM NONE

## IV. CHART CORRECTIONS

Corrective action affecting charts is contained in this section. Chart corrections are listed numerically by chart number. The correction listed pertains to that chart only. It is up to the mariner to decide what charts are to be corrected. The following example explains the individual elements of a typical correction.

Chart Chart Edition Last Local Notice

Current Local
number edition date to Mariners

Notice to Mariners

| | | | | | | | | |

03/95 ID - FRANKLIN LAKE - LEE HARBOR - PARKR WATERWAY -

(CGD13)

Add Parker Channel Light "2", Fl R 4sec 45FT 8M 48224'57"N 116220'30"W

Corrective Object of corrective

Position action action

The letter (M) immediately following the chart number indicates that the correction should be applied to the metric side of the chart only. (Temp) indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles.

18521 63rd ed., 12/28/96 LAST LNM 29/97 NAD 83 OR & WA - COLUMBIA RIVER - (CGD13)36/97

PACIFIC OCEAN TO HARRINGTON POINT

Change Astoria Basin North Light, to (Priv maint) 46211'23.4"N 123251'22.5"W

Astoria West Basin South Light, to (Priv maint) 46211'23.4"N 123251'16.5"W

18524 28th ed., 12/28/96 LAST LNM 29/97 NAD 83 OR - COLUMBIA RIVER - (CGD13)36/97

CRIMS ISLAND TO SAINT HELENS

Change Matthews Point West Light, to (Priv maint)

45<sup>2</sup>38'45.4"N 122<sup>2</sup>44'08.4"W

Matthews Point East Light, to (Priv maint)

45<sup>2</sup>38'45.4"N 122<sup>2</sup>44'00.4"W

18526 50th ed., 12/28/96 LAST LNM 29/97 NAD 83 OR - PORT OF PORTLAND, (CGD13)36/97

INCLUDING VANCOUVER

Change Swan Island Pier Light A, to (Priv maint)

45234'07.2"N 122243'25.9"W

Swan Island Pier Light C to (Priv maint)

45<sup>2</sup>34'05.4"N122<sup>2</sup>43'33.7"W

18531 18th ed., 02/19/94 LAST LNM 32/97 NAD 83 OR & WA - COLUMBIA RIVER - (CGD13)36/97

VANCOUVER TO THE DALLES

Change Hood River Marina Entrance East Light, to (Priv maint)

45242'50.0"N 121230'03.0"W

Hood Marina Entrance West Light, to (Priv maint)

45<sup>2</sup>42'50.8"N 121<sup>2</sup>30'08.1"W

18533 10th ed., 03/31/90 LAST LNM 26/97 NAD 83 OR & WA - COLUMBIA RIVER - (CGD13)36/97

LAKE CELILO

Change Tidewater Mooring Buoy A & B, to

(Priv Maint) (Priv maint)

45<sup>2</sup>40'12.4"N

120250'58.2"W

Tidewater Mooring Barge Lights A, to (Priv maint)

45<sup>2</sup>40'12.4"N 120<sup>2</sup>50'58.2"W

Tidewater Mooring Barge Light B, to (Priv maint)

45<sup>2</sup>40'10.0"N 120<sup>2</sup>51'02.0"W

## V. ADVANCE NOTICE OF CHANGES IN AIDS TO NAVIGATION

During the month of September 1997, Yaquina River Daybeacon 30 (LLNR 9725) will be discontinued. Yaquina River Buoy 30A (LLNR 9730) will be renumbered to Yaquina River Buoy 30. Chart 18581

## VI. PROPOSED CHANGES IN AIDS TO NAVIGATION

NONE

VII. GENERAL

DREDGING IN PROGRESS OR PLANNED WITHIN THE 13th COAST GUARD DISTRICT. MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION AND REDUCE THEIR WAKE WHEN TRANSITING THESE AREAS:

Location Area Start Complete Chart

Grays Harbor Cow Point 03/09/97 08/14/97 18502

Bar Middle Channel Willapa Harbor 07/25/97 08/15/97 18504

FISHERIES/BIOLOGICAL SAMPLING, PIER CONSTRUCTION, HYDROGRAPHIC SURVEYS. ETC., CURRENTLY IN PROGRESS WITHIN THE 13th COAST GUARD DISTRICT. ALL MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION WHEN TRANSITING THESE AREAS:

Location Area Start Complete Type of Work

Lk. Wash. Ship Canal Fremont Bridge 05/06/97 08/30/97 Scheluled

Maintenance

Lake Washington Evergreen Floating Bridge 06/01/97 09/17/97

Maintenance work

Tacoma Blair Waterway 01/28/97 To Be Announced 11th St. Bridge

Demolition

Snohomish River State Route 529 Bridges 05/06/97 To Be Announced

Replacement of old lift cables

WASHINGTON - PUGET SOUND - Marine Events - Puget Sound Area -

AREA/LOCATION DATE TIME EVENT SPONSOR PHONE # Clockwise around Guemes Island 09/13/97 1800-2300 Sail Boat Race Anacortes YC 293-5134

Sinclair Bay - Spring Beach 1000-1800 Sail Boat Race Sloop Tavern YC 09/13/97

783-2598

Port Madison/ Agate Pass/ Return 09/13/97 1100-1600 **Navigation Contest** Seattle

YC 454-9648

Meadow Pt 09/17/97 1800-2100 Sail Boat Race Corinthian YC of Seatle 789-

1919

Des Moines Marina 09/18/97 1800-2130 Sail Boat Race Three Tree Point YC 878-5514

1000-1700 West Point/ Meadow Point/ Shilshole 09/20/97 Sail Boat Race Sloop

Tavern YC 783-2589

Meadow Pt 09/24/97 Sail Boat Race Corinthian YC of Seattle 789-1800-2100

1919

1000-1500 Around Marrowstone Island 09/27/97 Sail Boat Race Port Ludlow YC

437-0814

Commencement Bay 1000-1400 Sail Boat Race Windseekers 838-09/27/97

5207

Lake Union 09/27/97 1200-1700 Sail Boat Race The Center for Wooden Boats

783-4851

Fort Flagler/ Colvos Rocks 09/28/97 1000-1500 Sail Boat Race Port Ludow

Yacht Club 437-0814

09/28/97 Des Moines Marina 1800-2130 Sail Boat Race Three Tree Point YC

878-5514

Lake Union 1200-1700 Sail Boat Race The Center for Wooden Boats 09/28/97

783-4851

OREGON - Marine Events - Portland Area -

AREA/LOCATION DATE TIME EVENT SPONSOR PHONE #

NONE

OREGON - WASHINGTON - COLUMBIA RIVER - Bridge Information -

The dual vertical lift spans of the I-5 Bridge at Vancouver, Washington, need not open for the passage of vessels from midnight 16 September until midnight 07 October 1997. The closure is for major mechanical repair. Mariners are requested to stay well clear of the drawspan channel during the project.

Large towing vessels with limited maneuverability will be passing via the alternate barge channel and the drawspan of the adjacent railroad bridge.

Chart 18524, and 18526

## WASHINGTON - LAKE WASHINGTON SHIP CANAL - Bridge Information -

The Montlake Bridge need not open both leaves of the drawspan for the passage of vessels unless 4 hours notice is given. Otherwise a single-leaf opening will be provided from 2200 local 06 September until 0600 local 07 September 1997. This special operations accommodates maintenance. Chart 18447

## WASHINGTON - PUGET SOUND - DUWAMISH RIVER - Bridge Information -

The drawspan of the 14th/16th Avenue Bridge at river mile 3.8 need not open for the passage of vessels unless two hours notice is provided from 0700 local to 1800 local from 15 September to 14 November 1997, while maintenance is being conducted.

## OREGON - NEHALEM RIVER - WATERWAY ANALYSIS - Request for Comments -

The Coast Guard is conducting an analysis of Hehalem River Entrance (Light List numbers 685, 9875, 9880, and 9885) to evaluate the adequacy of the aids to navigation. Users of this waterway are invited to comment on the current system. All comments should be received by 04 October 1799 at Commander, USCG Group Astoria, 2185 SE 12 Place, Warrenton OR 97416-9693, Attn: LCDR K. B. Jahnke. Addition, if you would like to participate in a survey being conducted on the waterway, fill out the information in enclosure (1) to this Local Notice to Mariners, and mail to the listed address. Chart 18556

# VIII. CORRECTIONS TO LIGHT LIST, VOLUME VI; PACIFIC COAST AND PACIFIC ISLANDS 1997:

(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)			
No.	Name	e and loca	ation	Positi	ion Chara	acteristic	Ht	Rng	Structure	Remark
	NON	Е								

## IX. ADDITIONAL ENCLOSURES:

1. Waterway Analysis for Nehalem River, Chart 18556, request for comment.

If you have any questions, comments, or need additional information concerning this or other LNMs or the LNM Mailing List (e.g. additions, deletions, corrections) contact the address or phone number on the front page.

## W. D. WIEDENHOEFT

Commander, U.S. Coast Guard
Chief, Aids to Navigation & Waterways Management Branch
Thirteenth Coast Guard District
By direction of the District Commander 2
COMMANDER, THIRTEENTH COAST GUARD DISTRICT
NOTICE TO MARINERS NO. 36

LOCAL

02 September 97 PAGE # OF 4	NOTICE NO. 36